

2

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME

Dinas

Report

Lir

No.

139437

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extracts from Sub-Committee's Report, 24/5/92.)

No. Special SURVEY PARTLY HELD.

Commencement

When due

9.53.

When proposed to be completed

4.54

Postponement approved

28/8/54

Portion of Survey held, &c.,

Spaces below boiler

Inlet

Subject to intended shell plates D3 & D4 from food (SS) being dealt with as necessary - repairs in main cross bunker being effected at the S.S. by 4.54.

Action is deferred for completion of 5/5

As now Subject



Lloyd's Register
Foundation