



LLOYD'S REGISTER OF SHIPPING

95, Bothwell Street, Glasgow, C.2

Telegrams: Register, Glasgow

Telephone: Central 6491 (4 Lines)

RECEIVED

30 MAY 1960

26th May, 1960.

Dear Sir,

Tug "FLYING SPITFIRE"

A fresh Interim Certificate was issued to the Owners on the 17th May containing the amended condition of class detailed in your letter of the 13th instant.


The Owners have now pointed out that this amended certificate is not strictly correct as the sternframe was not renewed above and below the boss, but that these parts were removed, faired and refitted and welded back in place.

In these circumstances it is suggested that the condition of class should now read as follows:-

"subject to the sternframe (E.W. above below boss 3,60) etc."

If you are in agreement with this will you kindly arrange for the Rpt.8 to be amended accordingly. A fresh Interim Certificate will be issued on receipt of your reply.

Yours faithfully,

for 
Secretary to the
Scottish Committee.

The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

011032-011036-0216

SR.

CLASSIFICATION

H *[Handwritten signature]*

[Handwritten signature]

LONDON
The Secretary

[Faint mirrored text]

of your letter. In connection with the above mentioned
matter, I have to inform you that the same has been
referred to the Committee on the subject of the
proposed amendments to the Bill.


Yours faithfully,
The Secretary

The Committee on the subject of the proposed amendments
to the Bill has considered the same and has decided
to recommend that the amendments should be
accepted with the following modifications:

1. The words "and the Secretary" should be
inserted at the end of paragraph 1 of the
Schedule.



© 2021
Lloyd's Register
Foundation



THE "LLOYD'S REGISTER OF SHIPPING"

RECEIVED

25, Broad Street, LONDON, W.1

LLOYD'S REGISTER OF SHIPPING