

4E

23 MAR 1956

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

S NAME "KOSTRENA"

REPORT

SPT.

No. 1932

Repairs to engines on account of vessel striking a rock.


Vessel examined afloat. Recommendations made for repairs,  
but no repairs done.

Vessel proceeding in tow to Rijeka.

IT IS SUBMITTED action be deferred.



© 2021 21.3.56.



011047-41056-0123

Lloyd's Register  
Foundation