

# Lloyd's Register of Shipping.



FOUNDED 1780.

RE-CONSTITUTED 1834.

## Certificate of Class

Twin Screw Steamer

"RIO GUADIANA"

Official Number — Port of Registry Rio de Janeiro

Owners E.G. Fontes & Cia.

Builders, and where and when built Launched by Lithgows Ltd., Port Glasgow, 1945.  
Converted and completed at Rio de Janeiro in August, 1954.

### REGISTERED PARTICULARS.

Length	330.0 feet	Tonnage, Gross	4033
Breadth	54.0 feet	Ditto under Deck	—
Depth	27.0 feet	Ditto Net	—

This is to Certify that this Ship has been surveyed by the Surveyors to this Society, and was reported to be, on the 10th August, 1954 in a fit and efficient condition as is prescribed by the Society's Rules for the safe carriage of dry and perishable or other approved Cargoes, and has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character **A1** For Service between Trinidad and the River Plate, with freeboard subject to Periodical Surveys as required by the Rules, and to 30 fathoms of chain cable of proper size, weight and test being supplied.

### THE FREEBOARDS FROM THE DECK LINE ARE AS FOLLOWS:—

Tropical	10 feet 8¼ inches (T).	Winter North Atlantic	— feet. — inches (WNA).
Summer	11 feet 0¼ inches (S).	Allowance for fresh water for all freeboards	4 inches
Winter	— feet — inches (W).		

Witness my hand,

*W. J. Ferguson*  
Secretary,


*R. L. ...*  
Chairman.

71, Fenchurch Street, E.C.3. 5th November, 1954.

N.B.—If the ship herein named proceed to sea with a less freeboard than that assigned, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

“ While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”



Lloyd's Register  
Foundation