

20 SEP 1960

by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

SEL'S NAME "S U K H A" REPORT Nfl. No. 4439

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

A SPECIAL SURVEY (C) became due in 6,55.

The Notation "Surveys Overdue 6,55" appears in the Register Book.

The ship was last docked in 11,51.

The ST.JOHN'S,Nfl., Surveyor reports (8,60), the ship placed in dry dock and a part Special Survey carried out to ascertain the condition and repairs necessary prior to putting the ship in service again.

Due to the extent and nature of the repairs required the Owner has decided to lay the ship up meantime pending a decision as to whether the necessary repairs will be effected.

IT IS SUBMITTED ACTION be DEFERRED pending receipt of further information.

IN R.B.
Surveys Overdue 6,55.



4439
© 19/9/60 2020

Lloyd's Register
Foundation