

15 APR 1957 550

Rpt. C. 11 (Contd.)

Index No. 37319
(For London Office use)

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name s.s. "LILLY" Official No.

Port of Registry Monrovia

This ship has been under survey at Amsterdam

on March 1957 and the following alterations to the conditions of

assignment of loadlines have now been effected/found:—

Original hatches 3 and 3A combined

Particulars of new hatch 3:

Opening : 25'0" x 20'0"

coaming : as original

stiffening beams : 10" x 3 1/2" x 44

spacing of cleats : 24"

hatchbeams : size as original

spacing: from forw. to aft. 4'6" - 5'10" - 3'7" - 3'7" - 3'4" - 3'9 1/2"

hatchcovers : as original

tarpsaulins : 3

LOCKING BARS FITTED.

E.D.H.F. Pronker
E.D.H.F. Pronker

Done 29.4.57

A copy of this Report has been placed on board.



© 2021

Lloyd's Register Foundation