

The previous history of this case is fully stated on Mr. G. Buchanan's endorsement dated 16.5.63.

DISCLOSED

13 JUN 1963

Ship's name *K/D/A*

SECTION

No. 780

Port

Port of Spain

No. 538

Class is subject to

Last survey date *15/5/63*

This ship has the notation in the R.B. 'thick' class suspended 3.55.

The Owners have now requested a certificate as an unclassified ship for one delivery voyage from Trinidad to the Persian Gulf. For this purpose the complete machinery installation was overhauled under the survey of Mr Mackillan, appointed by Lloyd's Agents, Venezuela.

The machinery was subsequently examined by the Port of Spain Surveyor who reports the machinery installation in good condition throughout.

Two new tested (Lloyd's) screwshafts were fitted at Maracaibo.

A machinery trial of unstated duration is reported as 'good'.

This report was issued for the information of the Committee.

Mr Sugger to note this report.

12/6/63

NB

The qualifications of the L.A. appointed Surveyor are not known in this Office.

Personnel please try to obtain particulars of this L.A. Surveyor.

End. E.2

011161-011170-0063

011161-011170-0064

hist. 28.6.63

© 2021
Lloyd's Register
Foundation