

by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

14 MAR 1950

US NAME 'M A I W A R A' REPORT H.Kg. No. 9797

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This vessel holds the provisional class of 100A1 (Reclassification Contemplated) and Notation of 'Examined 11.48' valid for 12 months.

The Notation of 'ss. Sh. 11.48(Dr)' is WITHHELD pending the completion of the Survey by repairs.

The class is subject to a stream anchor being supplied and 30 fathoms of worn chain cable replaced at the first opportunity.

The Owners proposal to postpone completion of the Reclassification Special Survey for 3 months was approved, provided a satisfactory survey be held without drydocking (See special endorsement 18.11.49).

The HONG KONG Surveyors report (12.49), vessel placed in dry dock, bottom coated, and minor repairs effected.

IT IS SUBMITTED for the consideration of the COMMITTEE in view of the validity of the 'Examined' Notation having expired 11.49, whether a record of docking 12.49 should be assigned.

} yes

IT IS FURTHER SUBMITTED ACTION and NOTATION of 'ss. Shi. 11.48(Dr)' be DEFERRED for completion of the Special Survey by 3.50.



© 2021 w.o.t. 9.3.50

Lloyd's Register  
S.S. Part Held.  
Foundation

011227-011234-0214