

2m, 9.52

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

"FLOATING CRANE NO.1"

Report

Lon.

A

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the repairs, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 2A/5/9)

Nature of Survey

When due

The 1st S.S.No.1 became due on this vessel

In reply to enquiry the Port Natal Survey

that the Owners do not wish to maintain the class of this

It is submitted the class of the vessel
from the Register Book and three dots (...) inserted in
indicating withdrawal of class at Owners' request.

Withdraw class

Insert ...



© 2021

Lloyd's Register
Foundation

, &c.:—
a notification of the
ship record of Survey,"
MD21, &c."

No letter from Owners agent