

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME

Empire Yarn

REPORT

Ad.

No.

51930

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Triple Expansion

If Boilers fitted with forced draught

Yes

Tail Shaft. If fitted with a continuous liner

Yes

If fitted with an outside gland of

approved type

no




This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, ^{most specifications} and it is submitted she is eligible to be classed *+ Rule 2.43*

Fitted for oil fuel 2.43. F.P. above 150°F

*Adm
18.3.43*

*Check dynamo test pump
or steam pump*



© 2021

Lloyd's Register
Foundation