

COPY

Ship's name

"LIBURNIA"

Port

PAL

No. 1098

Last survey date 5.7.64

Class is subject to

NONE

S.R.L. Appendix (as before ~~or none~~)

Nature of present survey (afloat and in drydock)

Deferred repairs to damage - cause not stated.


Recommendation

SUBMITTED record of DS 7,64. be assigned subject to indented shell plate No.5 in 5th below sheer (p.s.a.) being satisfactorily examined and dealt with as necessary by 12,64.

DS 7,64. Subject.

IN S.R.L. APPENDIX

No.3 plate in 3rd strake below sheer strake
(s.s. from fwd) slightly set in.
Stem plating slightly set in.
Shell plates E.3, D.3 (p.s.) indented.



© 2021

Lloyd's Register
Foundation

011259-01166-0132