

COPY

# LLOYD'S REGISTER OF SHIPPING



Port of GENOA

3rd July, 1961

This is to Certify that I have  
Surveyed the Machinery of the S/S "CROCE ITALO" 1,858 tons gross  
of Genoa, afloat and in drydock at Genoa on the 23rd June, 1961  
and subsequently for Docking and Commencement of MBS,

and that I will transmit to the Committee of Lloyd's Register of  
Shipping, London, a Report stating that all recommendations made by  
me in connection therewith have been carried out to my satisfaction; also  
that I will Recommend that in the case of this Vessel the following  
Survey Records be made in the Supplement to the Register Book  
MBS 6.61,

and that her Machinery Classification Record be continued in the Book.  
To complete the MBS the port boiler to be examined throughout,  
all the safety valves to be adjusted under steam and the main  
boilers to be examined in working condition together with the  
oil fuel burning installation and remote  
controls.

Parts now examined:  
(C.S. Items only)

(A. Ansaldo).

Engineer Surveyor to Lloyd's Register


## KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,3,59 (MADE AND PRINTED IN ENGLAND.)



Lloyd's Register  
Foundation