



## LLOYD'S REGISTER OF SHIPPING

Bellmansgatan 15,

Stockholm SÖ 31st March, 1960.

Issn. (S)

RECEIVED

2 - APR 1960

Ans d

The Secretary,  
LONDON.

Dear Sir,

We duly received your letter of the 11th instant relative to our report No. 12386 on the Motorship "ARBAN", and in reply have to acquaint you that the Forging Certificates for the main engine crankshafts were not sent with our report and were not included in the List of Certificates accompanying the report.

As these engines were built in Germany, we presumed that the Forging Certificates had previously been sent with Hamburg F.E. report No. 7502 on the main engines.

We may add that copies of the certificates in question have not been received in this office.

Yours faithfully,  
THE SURVEYORS, Stockholm.

c/e

CPSK.



© 2021

Lloyd's Register  
Foundation

011304 - 011315 - 0091



ΣΟ

CLASSIFICATION

H *NY* *and* *7502*  
*Request Hamburg*  
*forward chg*  
*to JFO* *12/4/60*

© 2021

Lloyd's Register  
Foundation