



LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

RECEIVED

21 OCT 1954

17 Battery Place,

New York 4, N. Y.

AIR MAIL

October 18, 1954

Dear Sir: "STELLA" No. 78685 in R.B.

The instructions contained in your letter of the 29th ultimo were transmitted to the Mobile Surveyor who advises that he called on board this vessel on her arrival.

However, due to the fact that the vessel was discharging, he was unable to carry out the Freeboard Survey. The Master stated that it was intended to have the Boiler and Annual Freeboard Surveys carried out on the vessel's arrival at Hamburg about the 24th instant. The boilers were under steam and could not be surveyed.


Yours faithfully,

Secretary to the American
Committee

The Secretary,

LONDON

cc Hamburg



© 2020

Lloyd's Register
Foundation

Periodical Survey, when the Survey should be a and subsequent report, other causes and be the replacement of Anchors

Orig
Cop

Lloyd's Register Foundation



NAME

ADDRESS

Reference, if any:

Dated 18.10.19

Vessel's Name:

The 1

Ultimo were t

he called on

Howev

he was unable

tated that i

reboard Sur

out the 24

would not be

.beverage ad ton

.Vladimir stroy

.victories ad

LONDON

grudman

LLOYD'S REGISTER OF SHIPPING

REGISTERED WITH THE BRITISH CORPORATION REGISTERS

11 Battery Place

Y. N. 4 400 Y W 91

4361, 81 10000

.B. R. 11 38387.00 "ALBERT"

that seavises who surveyor who letter of the seth
that seavises who surveyor who letter of the seth
that seavises who surveyor who letter of the seth

that seavises who surveyor who letter of the seth
that seavises who surveyor who letter of the seth
that seavises who surveyor who letter of the seth

Commissioner of the City of London

CLASSIFICATION

CLASSIFICATION

H 2

Copy 1000