

6m.9.61

4E

Class is subject to

22 JAN 1962

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME....."SANTA CECILIA".....REPORT.....Rio.....No. 8195.....

Docking. Screwshaft examined.

Screwshaft withdrawn for examination and white metal stern bushes found worn and now remetalled. Screwshaft removed to workshop and slightly skimmed and re-fitted.

In view of the satisfactory dry dock held at this time, the Surveyor submits that the condition of "Class Suspended" be removed and vessel reclassified LMC.

IT IS SUBMITTED that this vessel is eligible to be reclassified LMC and with fresh record of TS (B) 12. 61 now.



© 2021

Lloyd's Register  
Foundation

19.1.62

011378-011385-0160