

1m,10,33.

OLVINA X

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Screw Ketch "CAPE COMORIN" Rpt. Hul. No. 46829

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

1st Long. No. 2475

Depth "d" --

2nd Long. No. 7012.5

Proportions = $\frac{L}{D}$ 11.0

Framing Bulb angle frames as approved Sheerstrake As approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

100A1 'Steam Trawler'

1 Dk.

BK 7 $\frac{1}{2}$ ", 4 BH, Cem., Lloyd's A & CP.

Q 89' F27'



212 Sec. 4

25.5.26

Handwritten signature



© 2021

Lloyd's Register Foundation

011397-011407-0259

250



© 2021

Lloyd's Register
Foundation

REG

Length

Bread

Depth

FRAM

"

"

SIDE

Fra

Rev

De

Fra

Fr
Di

St

PAN

STR

SIN
F

M

DO