


LLOYD'S REGISTER OF SHIPPING



Port Helsingfors,

Date 15th July, 1963.

This is to Certify that I have

surveyed the **M.S. "YELKENCI"** **7046** Gross tons of Istanbul
 on the 12th July, 1963 whilst afloat in Kotka, for damage
 stated to have been caused by collision with quay side on
 10th July, 1963 at Kotka,

and that I am transmitting to the Committee of Lloyd's Register of
 Shipping, London, a report, stating that all repairs recommended by
 me have been completed to my satisfaction, also that I am
 recommending that she be retained as classed without fresh
 record of drydocking, subject to minor indent in shell
 plating port side No.2 hold aft end being specially examined
 and dealt with as necessary at next drydocking.

Jan Biedert

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BIS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	CSH	Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
 "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

