

Lloyd's Register of Shipping.

Ship's Name M.S. "WYRALLAH"

Official No.

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines in January, 1954.

1 - 2" scupper from Crew's W.C. (s.s.) in after deckhouse led overboard below freeboard deck with fabricated N.B. storm valve at ship's side.

1 - 4" discharge from Crew's W.C. (S.S.) in after deckhouse led overboard below freeboard deck with 5" G.M. storm valve at ship's side.

1 - 3" scupper from Crew's Washroom (p.s.) in after deckhouse led overboard below freeboard deck with G.M. storm valve at ship's side.

(Sgd) Thomas Nell

SURVEYOR TO LLOYD'S REGISTER OF SHIPPING.26th November, 1954.V. S. S.
10 DEC 1954

© 2021

Lloyd's Register
Foundation