

Ship's Name ~~SSMS~~ "CINDERELLA". Gross tons 6922  
LR507289  
Is there a rpt. 9? Yes. Port Antwerp Rpt. No. 41370  
No. of visits 2 First date I.9.65 Last date 2.9.65  
Interim Cert. issued & copy herewith? Yes. Damage rpt. issued & copy herewith? No. Last rpt. (H.Q. only) LA 56/57  
Date of completing rpt. 10.9.65 Surveyed at, if different from Port above -  
Surveyed afloat and/or in D.D. Afloat. Last date of examination in D.D. -  
Has a Load Line Survey been held? No. Freeboard Marks verified -

State which additional Rpt. 8 is attached: ~~COXX MPX XDRX XEQX XEXX~~

Survey fees

Damage fee

Expenses

frs. frs. 2000

frs 250  
S.A. feeI have surveyed the above ship in accordance with the Rules for WEAR & TEAR REPAIR.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

Shell plate G17 (ps) (from aft) found locally holed in upper seam (in N°1 Hold).

Plate cropped between frs. Nos.154-155 and part renewed. Hose tested on completion and found tight.

I recommend that this ship remain as classed with/without fresh record of dry docking subject to all conditions at present attached to the vessel's class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

D.A.R. CROWLEY

Surveyor to Lloyd's Register of Shipping

MONDAY - 8 NOV 1965

Deferred for 25 (by 1.66)  
D359.65 subject here.

ALSO FOR

SPL FOR

O.S.S.

TTCOPDS

DEPT.

SRL

POSTING

HEADER

CERT