

"CINDERELLA"

SUBMITTED a copy of Owners' Telex of 10th September and Secretary's reply of 13th September, 1965, be forwarded to the Surveyors at the repair port for their information. At the same time it should be pointed out to the Surveyors that the examination requested by the Owners is analogous to a docking survey, and all repairs considered necessary for confirmation of class until the S.S. in January next will require to be dealt with. It should be noted that the Owners, in addition, desire the deletion of existing recommendations, and with this in view the outstanding conditions of class as shown in S.R.L. No.240 should receive attention at this time, including any unrecorded damage affecting classification revealed at this survey.

*J. I.*  
14.9.65.



© 2021

Lloyd's Register  
Foundation

011433-011440-0085