

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex  
                          Overseas: Committee London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

## Enclosure

20th August, 1965

R  
NAB/GDF

Dear Sirs,

### M.S. "CINDERELLA"

I acknowledge your letter of the 17th August, the contents of which have been noted, and would inform you that the survey position is as follows:-

Special Survey due 1.65 (postponement until 1.66 approved) - vessel holds notation CSM 5.64.

Donkey Boiler Survey due 9.65.

Screwshaft Survey see below in connection with conditions of class.

Ship last seen in drydock 9.64.

The class is subject to the Screwshaft cone being specially examined at the next Special Survey or by the end of January 1966 (TS CL record of 9.64 withheld meantime) and to fractured shell plates Nos. 1 and 2 in third below sheer (port side) and No. 2 in third below sheer (starboard side) in way of AP. tank being specially examined and dealt with as necessary by the Special Survey.

With regard to the Continuous Survey cycle of the machinery, enclosed is a copy of the Society's Form 7E on which is shown the dates on which the various machinery items were last examined, those in black being the parts seen for the cycle completed 5.64, and those in red for the present cycle.

Lloyd's Register  
cont/...  
Foundation

011433-011440-0097 1/2



It will be noted from the Form that there are a few items which have not been examined for over four years (underlined) and these should be seen at an early opportunity. At the same time, I would remind you that the new cycle should be now advanced by about 25%.

Yours faithfully,

Clerk to the  
Classification Committee.

Messrs. ENCHIMAR,  
30, Boulevard Du Regent,  
Brussels,  
BELGIUM



© 2021

Lloyd's Register  
Foundation

0097 2/2