

COPY FOR LONDON OFFICE.

Lloyd's Register of Shipping.



Port

P A L E R M O

11th April, 1958.-

This is to Certify that I have
Surveyed the Boiler and ^{part} Machinery of the M/V "ALCANTARA",
5805 tons gross of Genoa, on the 6th March, 1958. and subsequently,
whilst vessel was in dry dock and afloat at Palermo,

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have
Recommended that the record of Donkey Boiler Survey 3/58.
Port Tailshaft Survey 3/58. Continuous Liner and Starboard Tailshaft
Survey (N) 3/58. Continuous Liner
be made in the Register Book in the case of this vessel when
the survey has been completed.

and to receive the notation
Continuous Survey of Engines 3/58.
Parts now examined:—

M.E. Nos.3 & 6 port cyls., covers, pistons and rods, valves and gears.
M.E. Nos.3 & 4 starboard cyls., covers, pistons, rods, valves & gears.
M.E. Nos.3 & 7 starboard journals & bearings.
Port & Starboard intermediate shafts & bearings.
Starboard holding down bolts & chocks.
General service and ballast pump, oil fuel transfer pump, both feed
pumps.
Pumping arrangements.
Independent electrically driven starting air compressor.
Port & starboard of daily service tanks.

(E. Grieves)


E. Grieves

P.T.O.

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."




Lloyd's Register
Foundation

COPY FOR LONDON OFFICE.

Lloyd's Register of Shipping
 First arrangements for the survey of the
 The port aft and starboard forward dynamo oil engines.
 The electrical equipment.

PALERMO

Port



11th April, 1958.

This is to Certify that I have

Surveyed the Boiler and Machinery of the M/V "ALCANTARA",
 2802 tons gross of Genoa, on the 6th March, 1958, and subsequently,

whilst vessel was in dry dock and afloat at Palermo,

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all

recommendations made by me in connection therewith have

been carried out to my satisfaction, and that I have

Recommended that the record of Dockyard Survey 3/58.

Port Tallshaft Survey 3/58. Continuous liner and Starboard Tallshaft

be made in the Register Book in the case of this vessel when

the survey has been completed.

Parts now examined:—

M.E. No. 1 & 2 port cyls., covers, pistons and rods, valves and gears.

M.E. No. 3 & 4 starboard cyls., covers, pistons, rods, valves & gears.

M.E. No. 5 & 6 starboard journals & bearings.

Port & Starboard intermediate shafts & bearings.

Starboard holding down bolts & shocks.

General service and ballast pump, oil fuel transfer pump, both feed

pumps.

Pumping arrangements.

Independent electrically driven starting air compressor.

Port & starboard of daily service tanks.

P.T.O.

(E. Gryves)

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
 "While the Committee of the Society use their best endeavours to ensure that the functions of the Society are properly executed,
 it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be
 held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register
 Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member
 thereof, or the Surveyors or other Officers or Agents of the Society."