

The class is subject to both propellers being renewed, and port seaconnection being renewed at the next drydocking.

4E

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor..... 13 MAY 1958

SHIP'S NAME "ALCANTARA" REPORT Pal No. 53

C.S. due 4.58, now completed.

DBS due 8.57, partly held 4.57, now completely re-held.

<sup>Repair</sup>  
Docking. Both screwshafts seen, and spare screwshaft fitted to starboard side, also both propellers now renewed. The port sea connection now renewed to be deleted from the SRL.

IT IS SUBMITTED that this vessel is eligible for THE RECORDS, CS 3.58,  
DBS 3.58,  
Port TS CL 3.58,  
Starboard TS N CL 3.58, without special condition.

8.5.58.

Lloyd's Register  
Foundation