

LLOYD'S REGISTER OF SHIPPING



RECD. 18. SEP. 1963

HAMBURG

Retain with Hamburg

Machinery First Entry

Port

MANNHEIM

Report No.

13516

SS/MS

"SAPELE"

9th September, 1963

R. Meier & Sohn,
y. No. 65

Works No. 17 E 2467
Order No. 20692/IWD/6725

This is to Certify that

Hubert Walkowiak

the undersigned Surveyor to this Society did at the request of
Messrs. Farymann Diesel, Farny & Weidmann, Lampertheim
attend at their works for the purpose of examining and testing
one auxiliary diesel engine, made to the order of Messrs.
Wiedemann & Walters GmbH., Hamburg.

Particulars of the engine are as follows:-

Engine Number..... 17 E 2467
Type E
Number of Cylinders 1
Diameter of Cylinders 75 mm
Stroke 100 mm
Maximum Pressure 55 kg/cm²
Mean Indicated Pressure 6.1 kg/cm²
Brake Horse Power 4.5 PS
Revolutions per Minute 1500
Span of Bearings 101 mm
Diameter of Journals 40 mm
Diameter of Crankpins 40 mm
Breadth of Webs 65 mm
Thickness of Webs 27 mm
Crankcase Volume..... 0.0075 m³
No. & Total Area of Crankcase -
Relief Valves if Fitted -

This engine has been built under Special Survey, in
accordance with the Approved Plans and Rules of the Society,
materials and workmanship being good.

On completion, the above machinery was tried in the
shops under working conditions with satisfactory results.

(see test report att.)

Particulars of identification marks:

Crankcase:

2467
Lloyd's Mhm²
TP. 10 kg/cm²
HW 29.8.63 HW

Crankshaft:

LLOYD'S DTM 7/9 HK

for Mr. Walkowiak:-

Fee:-

Expenses:-

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."