

COPY.

Lloyd's Register of Shipping.



Halifax, N. S.

March 19th, 1947.

LOAD LINE CERTIFICATE

This is to Certify that

R. M. SCOTT

The undersigned Surveyor to this Society did at the request of the Owners' Representative attend on board the Steel Single Screw Steamer "ARGOVAN" of Montreal (Ex. "TECUMSEH PARK" of Montreal) 163 tons gross afloat at Halifax Shipyards on the 21st March, 1947, for the purpose of issuing a Provisional Load Line Certificate in view of the ship's change of name.

The Freeboard markings on the ship's sides as shown below have been verified and found to conform with those assigned and set forth in the Load Line Certificate (Form L.L. 2, Canada No. 1777) issued by the Committee of Lloyd's Register of Shipping, under the authority of the Government of the Dominion of Canada and in accordance with the provisions of the International Load Line Convention, 1930, which Certificate was issued at London on the 15th December, 1943 and remains in force until 31st October, 1948.

FREEBOARD FROM DECK LINE		LOAD LINE
Topical	10' - 0" (T).	6 $\frac{3}{4}$ " above S.
Fore	10' - 6 $\frac{3}{4}$ " (S).	Upper edge of line through
Mid	11' - 1 $\frac{1}{2}$ " (W).	centre of disc.
Starboard		6 $\frac{3}{4}$ " below S.
North Atlantic)	not assigned	--

Allowance for fresh water for all freeboards 7 $\frac{1}{4}$ "

The upper edge of the deck line from which these freeboards are measured is NIL inches above the top of the Upper deck at side.

The back of this Certificate for last Annual Load Line Inspection.

This Provisional Load Line Certificate is valid pending the issue of an International Load Line Certificate by the Committee of Lloyd's Register of Shipping, London.

R. M. Scott
Surveyor to Lloyd's Register

This certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed and it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of the Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

