

# LLOYD'S REGISTER OF SHIPPING



Port La Guaira, Venezuela  
Date March 12, 1965

This is to Certify that I have

surveyed the **SS "LEONIDAS"** **13,406** of **Monrovia** on the **gross tons**

13th of Feb. 1965 whilst she lay afloat at Puerto Miranda, Lake Maracaibo for the purpose of examination of suspected grounding damage alleged to have been sustained on the 10th of Feb. 1965 at aprox. 0134 hrs. in the neighborhood of buoy 2 of Las Minas Bay Channel (Panama) whilst the vessel was proceeding at reduced speed to Payardi Island Marine Unloading Terminal with a shipment of oil.

and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating that all repairs recommended by me have been completed to my satisfaction, also that I am

recommending that she be retained as now classed subject to vessel's bottom be specially examined for possible grounding damage and repairs being dealt with as found necessary at next drydocking and subject to any outstanding condition of class being dealt with as previously recommended.

**Acting Surveyor**

**Lloyd's Agency  
Maracaibo**



Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

AS Annual Survey  
BiS Biennial Survey  
DS Docking Survey  
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey  
SS(Dr) Hull Special Survey (Drilling)  
SS(M) Hull Special Survey (Modified)  
SSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

© 2021

Lloyd's Register Foundation

011595-011602-0175