

COPY
LLOYD'S REGISTER OF SHIPPING



Port Balboa, Canal Zone

14 December, 1963.

Boa. Rpt. #5008.

This is to Certify *that I have surveyed part of the machinery of the S. S. "LEONIDAS" of Monrovia, Liberia, Gross tons 13406*

~~xxx~~ while afloat at Las Minas Bay, R. de P., and later at Cristobal, C. Z., on the 12th December, 1963, and upon subsequent dates, in order to examine and report upon damage to the propeller, alleged to have been sustained on the 9th December, 1963, as a result of the propeller striking a submerged object while on a voyage from Puerto Miranda, Venezuela, to Las Minas Bay, R. de P.

~~and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned~~ without fresh record of survey, subject to the ship's propeller being renewed before the end of May, 1964 (6 mos. limit).

Parts now examined:—

Acting

John G. Mallahan
Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CSM Continuous Survey of Machinery
DBS Donkey Boiler Survey
ES Engine Special Survey

MBS Main Boiler Survey
OF Fitted for oil fuel (date) FP above 150° F.
SGS Steam Generator Survey
SPS Steampipe Survey

TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."