

POSTPONED SURVEYS.

Case of the M.S. "VATNAJOKULL".

No. 89472. in Reg. Bk. tons, Built

Classed Lloyd's RMC-8.47 Owners
for temp 0°F to 16°F.

Subject to a spare shunt field coil for the air circulating fan being supplied. Port of Registry

Survey Due Modified Survey due 2.48.
(Complete Survey due 8.48).

In reply to enquiry regarding the Modified Survey and the supply of the spare shunt field coil for the air circulating fan the Society's Reykjavik Surveyor writes as follows:-

"During the repair of the main motor of this vessel I asked the Engineer about the Refrigerating System, and he told me, that the spare parts have been ordered a long time ago, also armatures for motors and etc., but the makers, have still not been able to deliver them. As soon as the spare parts will arrive he will call on me."

Submitted action by deference subject to the overdue survey being held before a refrigerated cargo is carried.

WED 21 JUL 1948

Committee's Minute *Deferred*

Decision

