



La correspondencia
debe dirigirse a los
Inspectores.



Lloyd's Register of Shipping,

OFICINA PRINCIPAL: FENCHURCH STREET, 71, LONDRES, E.C.3.

Calle de Ibáñez de Bilbao, 22,

RECEIVED Apartado de Correos No. 286,

14 MAR 1950

Bilbao, 10th March, 1950.

Dear Sir, ANSD.....

M.S. "TIO PEPE"

We beg to confirm the cable sent to you to-day
respecting our report No. 10648 on the engines of the
above Vessel, as follows:-


"TIO PEPE REFERENCE YOUR LETTER SIXTH INSTANT
"CONFIRM TWO INCH BRANCH SUCTION FITTED IN
"ADDITION DIRECT SUCTIONS AS APPROVED PLAN".

We regret that this item was not included in
our report.

We shall be glad if you will kindly forward
the Certificates to this Office.

Yours faithfully,

The Secretary,
LONDON.



Alpha Co.

Lloyd's Register
Foundation

011610-011618-0169

Referred to the Chief Engineer Surveyor.

D.O.
[Signature]

For Engineer Surveyors (F.E. Rpts.) to note.
See cablegram. End

R.2. "LLOYD'S"



© 2021

Lloyd's Register
Foundation