

Ship's Name SS/MS IWTA-SITARA NO. 97 Gross tons 60
Is there a rpt. 9? YES Port CHITTAGONG Rpt. No. 497
No. of visits 2 First date 29.9.63 Last date 8.10.63
Interim Cert. issued & copy herewith? YES Damage rpt. issued & copy herewith? NO Last rpt. (H.Q. only)
Date of completing rpt. 23.11.63 Surveyed at, if different from Port above CHALNA & NARAYANGANJ
Surveyed afloat and/or in D.D. AFLOAT & ON BOARD Last date of examination in D.D. -
Has a Load Line TRANSPORT VESSEL
Survey been held? NO Freeboard Marks verified -

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig)

Survey fees
Rs. 75/-

Damage fee

Expenses
Rs. 25/-

S.A. fee

I have surveyed the above ship in accordance with the Rules for GENERAL EXAMINATION.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

The vessel was examined on board the transport ship before landing in the water and found to be in good condition; the vessel examined afloat on delivery by sea to Narayanganj and no damage has been sustained.

I recommend that this ship/^{be} ~~remain as~~ classed ~~with/without fresh record of dry-docking~~ as contemplated

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

FRIDAY 24 JAN 1964

Minute

+ 100 AT East Pakistan Coasting Service

LACP

+ LMC ES
TS(B) } 8.63
(over)

(A. H. HIGNETT)

Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Lloyd's Register
Foundation

011619-011627-0181