

Rpt. 9A

REPORT OF MACHINERY SURVEYS AND REPAIRS

(ENGINES AND AUXILIARIES)

Received London

Ship's Name SS/MS IWTA-SITALAKHYA Gross tons 181.93  
 Is there a rpt. 8? YES Port CHITTAGONG Rpt. No. 504  
 No. of visits 2 First date 29.9.63 Last date 14.11.63  
 Interim Cert. issued & copy herewith? YES Damage rpt. issued & copy herewith? NO Last rpt. (H.Q. only)  
 Date of completing rpt. 25.11.63 Surveyed at, if different from Port above CHALNA & NARAYANGANJ  
 Is a rpt. 9B attached? NO MN Nature of survey H.E.  
 Survey fees Rs. 100/- Damage fee Expenses Rs. 25/-  
 S.A. fee

## MAIN ENGINES, RECIP., STEAM OR I.C. (State Port—P or Starboard—S)

1 Cyls., covers, pistons & rods  
 2 Valves & gears  
 3 Con. rods, top ends & guides centre Side  
 4 Crankpins & bearings centre Side  
 5 Journals & bearings

## MAIN ENGINE DRIVEN AIR COMPRESSORS (State Port—P or Starboard—S)

6 Cyls., covers, pistons & rods 7 Con. rods & top ends  
 8 Crankpins & bearings 9 Journals & bearings  
 10 Coolers & safety devices

## MAIN ENGINE DRIVEN SCAVENGE PUMPS (State Port—P or Starboard—S)

11 Cyls., covers, pistons & rods 12 Con. rods & top ends  
 13 Crankpins & bearings 14 Journals & bearings

## MAIN TURBINES (State Port—P or Starboard—S)

16 Casings, rotors, blading, bearings & thrusts 15 Levers

17 Reduction gearing  
 18 Scavenge blowers 19 Superchargers

I recommend that the machinery of this ship <sup>be</sup> ~~remain as classed with/without fresh records of~~ as contemplated.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

(A. H. HIGNETT)  
 Surveyor to Lloyd's Register of Shipping

Date of Committee

FRIDAY 13 DEC 1963

Minute

+ LMC ES } 8-63  
 Ts(08)  
 p4s

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT



Lloyd's Register  
 Foundation

011628-011635-0023.7

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

considered that re-examination or repairs should be made before that date a distinguishing mark must be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is

20	Exhaust steam turbines (with recip. eng.)	21	Thrust blocks shafts & bearings		
22	Steam compressors	23	Intermediate shafts & bearings		
24	Clutches & hydraulic couplings	25	Condensers (main & aux.)		
26	Steam re-heaters	27	Air ejectors (main & aux.)		
28	De-superheaters	29	Forced &/or induced draught fans		
30	Stop & manoeuvring valves	31	Holding down bolts & chocks	32	Detuner or vibration damper
33	Main engine driven pumps				
34	Crankcase doors & explosion relief devices			35	Have main engines been tested working & manoeuvring? (To be done on completion of ES or CS cycle)

State Port P. or Starboard S.

36 Essential independent pumps

35 Have main engines been tested working & manoeuvring? (To be done on completion of ES or CS cycle)

37 Bilge, ballast & oil fuel suction lines, fittings & controls

38 Have the remaining piping arrangements & fittings in the machinery space been examined as considered necessary?

39 Fresh water coolers

40 Lub. oil coolers

41 Heaters (state service)

42 Feed water filters

43 Auxiliary air receivers & safety devices

44 Starting air pipes

45 Main air receivers & safety devices

46 Independent air compressors coolers & safety devices

Identify by position

47 Oil fuel tanks (not forming part of the hull structure)

48 Have all evaporators safety valves been tested under steam?

49 Evaporators HP & LP

50 Distillers

51 Fire extinguishing arrangements

52 Steering machinery


53 Windlass

AUXILIARY ENGINES

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

Both propellers and stern fastenings examined on board the transport vessel before landing in the water and both main engines and all auxiliaries examined afloat at Narayanganj after transport to its working area. All machinery found to be in good condition.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should also be reported above.



© 2021

Lloyd's Register Foundation