



Lloyd's Register of Shipping

48 DALHOUSIE STREET,

QUEBEC, February 13, 1943.

A..R. Riddell, Esq.,
MONTREAL.

Report No. 5743
S. S. "GATINEAU PARK"
Hull No. 535

Dear Sir:

In reply to Classing Letter dated 29th. December, it is confirmed that the weather decks, bulkheads and tunnel have been hose tested as required by the Rules and the windlass and steering arrangements tried under working conditions. An echo sounding device is installed and was adjusted by specialists during the River trial.

In ships not completed before receipt of London letters of 30th. July and 12th. August, the instructions given therein have been carried out and in future reports we will insert particulars of the tween deck, bulkhead numbers, position, scantlings and also the openings therein and the method of closing.

Trusting this information will be found complete and satisfactory.

Yours very truly,

A. Hislop
SURVEYOR.



*copied for
"Banff Park"*

AH/P.



© 2021

Lloyd's Register
Foundation

011646.011656-0012

Noted
L.C.D.
2.4.43



© 2021

Lloyd's Register
Foundation

Im 937

Received

VESSE

The

1

2

F

R

b

F1

11

B

ex