

4E

12 JUL 1957

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

"MAX MANUS"

REPORT

Rot.

No.43607

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/52.)

Survey REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

DBS due 3,57, now held.

Docking. Screwshaft seen.

Repairs. CS. complete.

IT IS SUBMITTED that this vessel is eligible for the record DBS 5,57, TS CL 4,57. + record CS 5:57

*MH*  
*at*

10.7.57



© 2021

Lloyd's Register  
Foundation

011646-011656-0212