

Received from Chief Ship Surveyor

14 OCT 1954 BC

SHIP'S NAME

"PORJUS"

REPORT

Got.

No. 20965

Standing Conditions of Class:

Subject to a bow anchor (p.s.)
being renewed at the earliest opportunity.

Endorsement of Class (B) (As before ~~or None~~)

Nature of Present Survey: (Afloat ~~and~~ in dry dock)

Docking: Damage (cause not stated) involving indented bottom and side shell plating (p & s).

Recommendation:

SUBMITTED record of docking 9,54 be assigned, subject as above, and to indented bottom and side shell plating, etc. (p & s) being dealt with as necessary by next Special Survey, with Endorsement (B)

9,54 Got. Subject.

ENDORSEMENT OF CLASS (B).

Indents in keel and shell plating (p & s). //

IT IS FURTHER SUBMITTED the Surveyors be informed it is concluded that the damage now reported to the bottom and side shell plating is situated on the port and starboard sides, but confirmation is desired as this information has been omitted from the report.

011657-011664-0081

Lloyd's Register
Foundation