

subject to Main sw. circulating pump motor armature shaft being renewed **4E**  
at London with the ship proceeding.

7 JUN 1960

ed by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

'S NAME *ss. 'MANDAGALA'*.....REPORT *London*.....No. *142590*.


Docking, Damage, Repairs.

Damage stated here correct lock-wall 10/4/60.

SKL. The above item built into and to be deleted.

Propeller repaired.

main circulating pump repaired.



It is submitted that this  
vessel is eligible to remain  
as **CLASSED.** Without special condition.

*rec*  
*3/6/60.*



© 2021

Lloyd's Register  
Foundation

011665-011670-0157