

COPY

LLOYD'S REGISTER OF SHIPPING

5 MAY 1960

Port LONDON

28th April, 1960

This is to Certify that I have

examined the Machinery of the S.S. "MANDAGALA" 7681 tons gross of
on account of a Condition of Class in respect of the
circulating pump armature shaft, and damage to the pro-
per said to have been sustained by contact with the side
that I will transmit to the Committee of Lloyd's Register of

P.T.O.

ing, London, a Report stating that all recommendations made by
connection therewith have been carried out to my satisfaction; also

I will Recommend that in the case of this Vessel the following
retained
Records be made in the Supplement to the Register Book
out fresh record of survey and without special condition
respect of the main circulating pump armature shaft.

that her Machinery Classification Record be continued in the Book.

ect to any outstanding conditions of class being dealt
as previously recommended.

now examined:

8. Items only)

H. Draggitt

Engineer Surveyor to Lloyd's Register

H.B. DRAGGETT.

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CS Continuous Survey of Engines
DBS Donkey Boiler Survey
ES Engine Special Survey
MBS Main Boiler Survey
MES Modified Survey of Oil Engines
OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
SPS Steampipe Survey
TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

ificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be
that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any
in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society
error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents
ty."

LOYD'S REGISTER OF SHIPPING

COPY

Port

This is to Certify that I have

of Latchford Lock in the Manchester Ship Canal at
hours on 10th April, 1960, whilst en route from
to London in part loaded condition.

connection therewith have been carried out to my satisfaction; also

will Recommend that in the case of this Vessel the following

Records be made in the Supplement to the Register Book
the record of survey and without special condition
of the main classifying pump arrangement.

her Machinery Classification Record be continued in the Book.

examined:
(Items only)


Engineer Surveyor to Lloyd's Register

[Signature]

KEY TO ABBREVIATIONS

AGS	Continuous Survey of Engines	AGS	Continuous Survey of Engines
DBS	Donkey Boiler Survey	DBS	Donkey Boiler Survey
ES	Engine Special Survey	ES	Engine Special Survey
MRS	Main Boiler Survey	MRS	Main Boiler Survey
MES	Modified Survey of Oil Engines	MES	Modified Survey of Oil Engines
TS	Tailshaft Survey	TS	Tailshaft Survey
TSN	Tailshaft Survey—Continuous Line	TSN	Tailshaft Survey—Continuous Line
TS(C)	Tailshaft Survey—Continuous Line	TS(C)	Tailshaft Survey—Continuous Line
TS(O)	Tailshaft Survey—Oil Gland	TS(O)	Tailshaft Survey—Oil Gland
SGS	Steam Generator Survey	SGS	Steam Generator Survey
SPS	Steam Pipe Survey	SPS	Steam Pipe Survey
TS	Tailshaft Survey	TS	Tailshaft Survey

is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
The Committee of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be
the duty of the Society to ensure that the functions of the Society are properly executed, it is to be
the duty of the Society to ensure that the functions of the Society are properly executed, it is to be



© 2021

Lloyd's Register
Foundation