


COPY

LLOYD'S REGISTER OF SHIPPING



Port Balboa, Canal Zone

Date 30 December, 1964.

Report #5295.

This is to Certify that I have

surveyed the M. S. "HAKONESAN MARU" 6927 Gross tons of Tokyo, Japan, after damage to main deck bulwark rail and stanchions, bridge deck awning frames, bulwark and railing and Lifeboat No. 2, davits and chocks (all port side) stated to have been sustained on 30 December, 1964, whilst ship lay afloat at Pier 16, Cristobal taking bunkers and was struck by M. S. "JARITA" which had been unberthed and was in the process of passing the "HAKONESAN MARU" -

and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating ~~that all repairs recommended by me have been completed to my satisfaction also~~ that I am recommending that she be continued as now classed -

-100A1

without fresh record of docking, subject to necessary repairs and renewals being made to port side bridge and main deck bulwarks and stanchions, and the No. 2 Lifeboat and davits upon vessel's arrival at a convenient Japanese port to where she is now proceeding.

[Signature]
Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

AS Annual Survey
BIS Biennial Survey
DS Docking Survey
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
SS(Dr) Hull Special Survey (Drilling)
SS(M) Hull Special Survey (Modified)
CSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B 80m,4,62 (MADE AND PRINTED IN ENGLAND.)

© 2021 Lloyd's Register Foundation
011671-011677-0177