

EA

19 JUN 1964

Ship's name "BEECH HILL"

Port

RGN.

No. 06407

Last survey date 3.6.64

Class is subject to set in shell plates No.3 in 2nd and 3rd strakes below sheer (s.s.f), indented shell plates F.6, G.4 & 5, H.5 etc. (p.s.f) and inner bottom plating in No.5 hold, also to forward bulkhead of No.5 hold (s.s)(holed) also indented shell plates G.8 and H.9 (p.s) being specially examined and dealt with as necessary by the S.S., and to a bower anchor being supplied at the earliest opportunity. ACTION is DEFERRED for S.S. by 5,64.

S.R.L. Appendix (as before ~~on xxxxxx~~)

Surveys due S.S.(C) due 5,63. Postponement until 5,64 approved 21.11.63. G.E. held Pir.9,63. Further postponement until 7,64 approved 8.5.64 provided a further G.E. is held. A still further postponement until end of 8,64 approved 17.6.64 to allow the ship to reach her final discharge port. See Owners letter of 15.6.64 and London cable of 17.6.64.

Nature of present survey (afloat ~~and in drydock~~)

G.E. as above.

Temporary repairs on account of leakage.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS

SS proposed to be completed by

Recommendation SUBMITTED ACTION continue to be DEFERRED for S.S., subject as above and to leaky shell rivets in way of frame NO.148 in shell plate F.15 (s.s) in No.1 hold, wasted bottom shell plate in way of No.1 starboard bilge striking plate and leakage in way of port and starboard fuel oil deep tanks all being specially examined and dealt with as necessary by the S.S.

SUBJECT

IN S.R.L.APPENDIX

Top of starboard ~~hawse~~ pipe E.W.

IT IS FURTHER SUBMITTED postponement of the Special Survey until 8,64 merits approval.



© 2021
Lloyd's Register
Foundation
18/6/64