

2nd August, 1962.

STOCKHOLM.

13731 "BEECH HILL" - As recommended.

As you were advised by the Rotterdam Surveyors of the remaining items to complete the Main Boiler Survey, it is concluded that the safety valves of all three boilers were adjusted under steam. Your Rpt. 9 refers only to the port boiler, and I shall be glad to have your confirmation that the safety valves of the other two boilers were also adjusted.



© 2021

Lloyd's Register
Foundation

011712-011717-0270