



# LLOYD'S REGISTER OF SHIPPING

OFICINA PRINCIPAL: FENCHURCH STREET, 71. LONDRES, E. C. 3.

Calle Gran Vía, 83, 1.º izqda.

RECEIVED

Apartado de Correos N.º 286, Bilbao

Telegramas: Register, Bilbao

16 DEC 1958 11th December, 1958

Teléfono 16995

La correspondencia  
debe dirigirse a los  
Inspectores  
Classn(S)

Ans'd.....

Dear Sir,

Motorship "JOSELIN"  
Bilbao First Entry Report  
Nº 12426

In reply to your letter of the 2nd inst., we feel that our recommendations on the above report could have been clarified as follows: "-subject to 20 KW generator set (Nº 3 port aft) being tested under working conditions when automatic voltage regulator is fitted".

We understand that an automatic voltage regulator was subsequently fitted and arrangements will be made for testing under working conditions on the vessel's next visit to this port.

Yours faithfully,

The Secretary,  
LONDON

*[Signature]*

0700-596110-152110

CLASSIFICATION

H  
M R. Y.

Y.H.  
17/10/58

© 2020

Lloyd's Register  
Foundation

