

AIR MAIL  
COPY

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen. London

Telephone: ROYal 3551 (6 Lines)

## Enclosures

2nd June, 1955.

Dear Sir,

Classn(S)  
RNC

CONTRACT 646 - BLUFF HARBOUR BOARD  
ROCKBREAKER PONTOON.

I have your letter of the 20th April, and am obliged to you for the information now furnished.

In reply to your enquiry I would inform you that a Rpt. 4 and Rpt. 13 should be forwarded here on completion of your survey.

With regard to the second page of your letter, before replying to your enquiry it will be necessary for you to supply full information as to whether the boiler was severely or otherwise affected by the fire.

I would also take this opportunity to acknowledge your airletter of the 22nd April and with regard to Drawing No. 2792, which is returned herewith, I shall be glad to receive your comments on the following apparent divergencies from the specification:-

- 1) No provision appears to have been made for the navigation lights referred to in paragraph 3 (i) of the Contract.
- 2) The cables are stated to be Pyrotenax, whereas lead covered cables are specified in the penultimate paragraph of page 7 of the Tender forming part of the Contract documents.

The enclosed plans should be returned to this Office in due course with your electrical report on form Rpt. 13.

Yours faithfully,

Deputy Clerk to  
the Classification Committee.

BUNEDW:ite, Esq.,

© 2021

Lloyd's Register  
Foundation