

COPY

# LLOYD'S REGISTER OF SHIPPING



Port of Genoa

3rd May, 1961

**This is to Certify** *that I have*

*Surveyed the Machinery of the M/V "SERGIO LAGHI" 10495 gross tons of Genoa, whilst lying afloat and in drydock at this Port on the 13th April, 1961 and subsequently for Docking Survey, Advancement of CS, ABS & Repairs, and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book CS (with date) on completion of survey, and ABS 4.61 and that her Machinery Classification Record be continued in the Book.*

**Parts now examined:** In drydock :- Propeller, after end of stern bush and outside fastenings.  
(C.S. Items only)

Main engine N° 2, 3, 5 & 6 cylinders, liners, pistons, covers with valves & gears.

N° 3 top end, crosshead, connecting rod & guides.

N° 2 & 3 bottom ends and crankpins.

N° 7 crankjournal & bearing.

Inboard S.W. main circulating pump, ED.

Aft F.W. main circulating pump, ED.

Auxiliary steam condenser.

( S. Follo ). Engineer Surveyor to Lloyd's Register


### KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,3,59 (MADE AND PRINTED IN ENGLAND.)



011800-011804.0454