

DEC 1964

Ship's Name ~~SS~~/MS "PEA COCK"

Gross tons

Is there a rpt. 8?

Port Liverpool

Rpt. No. 165242

No. of visits

First date

Last date

Interim Cert. issued & copy herewith?

Damage rpt. issued & copy herewith?

Last rpt. (H.Q. only)

Date of completing rpt.

Surveyed at, if different from Port above

Is a rpt. 9A attached? Yes

MN

Nature of survey

Docking and Completion of C.S.

Survey fees

Damage fee

Expenses

S.A. fee

DOCKING

Propeller Good

Sea connections Good

Oil gland Good

Fastenings Good

Wear down of stern bush .038"

Has screw/tube shaft been drawn? No

Date of examn. -

Has shaft been changed? -

Has shaft now fitted been previously used? -

Has shaft now examined/fitted a continuous liner? - Approved oil gland? Yes

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG) MAIN

Air heaters

Superheaters

Safety valves

Mountings, doors and fastenings

Safety valves adjusted to { Sat Spt

Boiler securing arrangements

Main economisers

Exhaust gas heated economisers

Steam heated steam generators

Steam generator safety valves adjusted to

Forced circulating pumps

Funnel

Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules?

Were oil burning system & remote controls examined in accordance with rules?

I recommend that the machinery of this ship remain as classed with/without fresh record of

Recommendation see Rpt. 9A attached.

ALSO FOR

SPL FOR

TRO

SRL ✓

POSTING

HEADER


CERT

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

J. White. Surveyor to Lloyd's Register of Shipping

Date of Committee LIVERPOOL - 8 DEC 1964 J. White.

Minute See 9A



Lloyd's Register Foundation

011813-011822-0143

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

considered that re-examination or repairs should be made before that date a distinguishing mark must shortly be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is