

Chief Surveyors.....

Received from Chief Surveyors.....

NAME

WINAMAC

REPORT

Boston

No 4793

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.).

Survey.....

When due

Before this case is confirmed, Boston Surveyor should be asked to state if the auxiliary engines driving the dynamos were examined at this time.

noted

J.K.

28 JAN 1958

J.K.



© 2021 10 JAN 1958

Lloyd's Register
Foundation

011823-011825-0076