



# LLOYD'S REGISTER OF SHIPPING

17 Battery Place,

New York, N. Y. 10004

March 18, 1964

20 MAR 1964

The Secretary

LONDON.

Dear Sir,

"SHELL MANAURE"


We would refer to the Curacao Surveyor's Rpt. 8, No. 6922, which is being forwarded to you under separate cover.

When this report was received in this office we requested the Curacao Surveyor to provide us with his comments regarding the reason for fitting the Exhaust from the Deisel Generator through the Sheer strake and not led up the funnel as is generally the case.

It is noted that a copy of the Surveyor's Report dated the 5th March has already been forwarded to you.

Perhaps you will be good enough to keep this office advised regarding any action which may be taken.

Yours very truly,

  
W. J. ROBERTS  
Chief Representative and  
Principal Surveyor

WFS;hd

F



© 2021

Lloyd's Register  
Foundation

011834-011843-0067

REPORTS

*MLL*



© 2021

Lloyd's Register  
Foundation