

Helmsdon control from bridge also local control

Emerson Walker

11 0 APR 1948

hains  
Req. II. <sup>Wlds.</sup> ~~W~~ <sup>ys.</sup> (Received at London Office.....)

No. ~~#~~ <sup>E</sup> Port **MIDDLESBROUGH** Date **7<sup>TH</sup> APRIL** 19 **48**


**WE** request that the **STEEL TWIN SCREW OIL TANKER.** Building

for **ANGLO SAXON PETROLEUM Co** by **SMITH'S DOCK CO LTD SOUTH BANK.**

of **—** Tons. Length, **382'-0"** BP. breadth, **62'-6"** MLD. depth, **18'-9"** MLD.

may be Specially Surveyed while building ( **✕ 100 AI.** **CARRYING PETROLEUM IN BULK.** ) If for a particular term or class, state the same

**WE** hereby engage to pay the established Special Survey Fees or any other charges from which has been duly notified and, in addition, any travelling and other expenses which may be incurred by the Surveyors in connection with the survey.



This request is made upon the terms of the Rules and Regulations of Lloyd's Register, of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

No. **EW. 1214** in Builder's Yard. manufacturers of Engines **SMITH'S DOCK CO LTD SOUTH BANK.**

Ditto of Boilers **BABCOCK & WILCOX.**

Signature **B. E. Bunker**  
FOR SMITH'S DOCK CO. LTD  
SHIPYARD MANAGER.

To the Secretary,  
Lloyd's Register of Shipping,  
71, Fenchurch Street, London, E.C.3.

VOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—  
"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

att' 144

011834-011843-0077