

6 - MAR 1962

Received from Chief Ship Surveyor.....

SHIP'S NAME "SHELL MANUABE" REPORT CCO No. 6402

EA

Standing Conditions of Class: SUBJECT to set in sheerstrake plating etc. in way of Nos.1 & 4 wing tanks (s.s.) being dealt with at the next drydocking.

ACTION is DEFERRED for examination in dry dock after grounding.

L. Appendix. ~~(As before)~~ or None)

Particulars of Present Survey: (Afloat and in dry dock)

Docking:- Damage repairs (various causes) and to the deferred item as above.

Recommendation: SUBMITTED record of DS 12,61 be assigned, without special conditions.

DS 12,61 Without.

~~DELETE FROM S.R.L.  
Drydocking (grounding).~~

IT IS FURTHER SUBMITTED the Surveyors be advised it is concluded that the requirements of Circ.No.2106 dated 27.11.57 have been complied in conjunction with the measuring at this time of the shell plating and internals with audiogauge but confirmation is desired, and if possible to furnish the actual thickness ascertained by drilling.

C.S.S. Records Dept.

to note. Shell and deck plating thicknesses measured by audiogauge.

011834-011843-0085

7/0  
See letter dated 21-3-62.

© 2021  
Royal's Register  
Foundation  
27-2-62