

11 MAY 1958

Received from Chief Ship Surveyor.....

SHIP'S NAME "WORLD PEACE" REPORT Msl. No. 12364

Standing Conditions of Class: Subject to sternframe (E.W. & reinforced 9,53) being specially examined at next drydocking.

Endorsement of Certificate (As before or None)

Surveys due: SPECIAL SURVEY (B) due 9,57. Postponement until 3,58 approved 4.2.58.

Nature of Present Survey: (Afloat and in dry dock)

Docking: Special Survey: Wear and tear repairs: Damage repairs (various causes): Examination of deferred items as above.

Special Features:

Interim Certificate in order (Yes-No-None)

Items Outstanding: (If any for S.S.)

NONE.

to be completed by

Recommendation:

SUBMITTED record of 'DS 3,58' and Notation of 'SS Msl. 3,58' be assigned, without special conditions but with Endorsement of Certificate.

DS 3,58
SS Msl. 3,58 Without.

ENDORSEMENT OF CERTIFICATE

Indents in shell plates in 3rd below sheer (s.s.) and in 2nd below sheer (p.s.f.).

IT IS FURTHER SUBMITTED the Surveyors be requested to advise whether, as a result of this present survey, the condition of class regarding sternframe may now be deleted.

Cert. Msl. X 4/5



© 2021 Lloyd's Register Foundation

011884 - 011889 - 0076