



A new form should be prepared if any alterations that affect the freeboard have been made. If no such alterations have been made, the Surveyor should endorse the form on this side with his signature and the date.

*[Faint, mostly illegible text and markings, possibly bleed-through from the reverse side of the page.]*

**Displacement and Tons per Inch at Intermediate Waterlines**

	<u>Displacement</u>	<u>T.P.I.</u>
13' W.L.	1961	14.70
14' W.L.	2138	14.92
15' W.L.	2317 ✓	15.17
		00.00
		00.00
		00.00
		00.00
		00.00
		00.00
		00.00

Trade of ship International

Names of sister ships S.S. "OTTAWA PANDA" - Pacific Drydock Co. Ltd's Yard No. 158

Builder's name and yard number Prince Rupert Drydock & Shipyard - Yard No. 58

Owners Minister of Munitions and Supply of Canada. ✓

Fee \$40.00 ✓