

Prime Movers. has the governing been found as per Rule when full load is thrown on and off. Yes Are turbin

"T A N B"

=====

The electrical equipment of this vessel has been fitted on board under Special Survey, tested under working conditions and found satisfactory.

The materials and workmanship are good.

Last date of survey 30.3.49.

J. Hafner

11th April. 1949.

=====



© 2021

Lloyd's Register
Foundation

011896-011904-0114 ed T

make of fuses. "Artic" are all fuses labelled Yes If circuit breakers are provide